ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
1

Ward Name
Kempegowda Ward

Street ID
W0492, W0415, W0409, W0417, W0411, W0498, W0494, W

Street Name
NA, Mani Lyt 2nd Main Rd

Significant Landmark
KHB Colony and Nehur nagara

Segment No.
1/C-W0492/S111943

Total Length (m)
516.15

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	49.54	77.596708	13.096665	77.596672	13.096219	W0498	W0494
2	50.95	77.597081	13.096626	77.597031	13.096168	W0498	W0494
3	51.16	77.597475	13.096580	77.597395	13.096124	W0498	W0494
4	205.18	77.595951	13.096815	77.597830	13.096603	I0359	RI-A17
5	159.32	77.596237	13.097314	77.597690	13.097102	I0359	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to Roads and Drains at KHB Colony and Nehur nagara in ward no 01 Yelahanka Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
1950000

Sanctioned Year
2014

Year
2014 - 2015

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements to Roads and Drains at KHB Colony and Nehur nagara in ward no 01 Yelahanka Sub-Division Yelahanka zone

Job No. / Work Code
001-15-000015

Work Order No.
EE(YNK.D)/E-PMT-4/WO/21/2014-15

Work Order Date
08/01/2015

Period of Extention
90 DAYS

Defect Liability Period From
08/01/2015

Defect Liability Period To
04/01/2016

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)

Phone No.	E-Mail ID
9845396612	

Field Inspection Details

Number of Trees	Any Other Information	Name
11		CHANDRASEKHAR
Date of Inspection	**Remarks**	
03/12/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0492, W0415, W0409, W0417,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	03/12/2016	02/01/2017	COMPLETED
SE	VASU K M	03/12/2016	02/01/2017	COMPLETED
EE	SRINIVAS	03/12/2016	02/01/2017	COMPLETED
AEE	G.B. PRABHAKAR	03/12/2016	02/01/2017	COMPLETED
AE	CHANDRASHEKAR	03/12/2016	02/01/2017	COMPLETED
AE	CHANDRASHEKAR	03/12/2016	02/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0492, W0415, W0409, W0417,